

Turning - Cutting data



Nomenclature and formulae



RPM	$n = \frac{v_c \cdot 1000}{\pi \cdot D}$	(rev/min)	a_p = Depth of cut	(mm)
Cutting speed	$v_c = \frac{n \cdot \pi \cdot D}{1000}$	(m/min)	D = Workpiece diameter	(mm)
Surface finish	$R_a = \frac{f^2 \cdot 50}{r_E}$	(μm)	f = Feed rate	(mm/rev)
	$R_a = \frac{R_t}{3,5}$	(μm)	h = Chip thickness	(mm)
	$R_y = \frac{f^2}{8 \cdot r_E}$	(μm)	k = Constant. 1.4 for steels and stainless steels and 1.0 for cast iron	
Profile depth	$R_t = k \cdot \frac{f^2 \cdot 1000}{8 \cdot r_E}$	(μm)	k_C = Specific cutting force	(N/mm ²)
Power demand	$P_C = \frac{v_c \cdot f \cdot a_p}{25}$	(kW)	$k_{C1.1}$ = Cutting force (1 mm ²) (See page 252)	(N/mm ²)
	$P_C = \frac{v_c \cdot f \cdot a_p \cdot k_C}{60\,000 \cdot \eta}$	(kW)	mc = Exponent (See page 252)	
	$k_C = \frac{1-0,01 \cdot \gamma_0}{h^{mc}} \cdot k_{C1.1}$	(N/mm ²)	n = RPM	(rev/min)
	$h = f \cdot \sin \kappa$		P _C = Power demand	(kW)
Metal removal rate	$Q = v_c \cdot f \cdot a_p$	(cm ³ /min)	Q = Metal removal rate	(cm ³ /min)
			R _a = Surface finish	(μm)
			r _E = Nose radius	(mm)
			R _t = Profile depth	(μm)
			R _y = Max. height of profile	(μm)
			v _c = Cutting speed	(m/min)
			κ = Setting angle	(°)
			η = Efficiency	
			γ ₀ = Cutting rake angle	(°)