



Instruction Leaflet

Plug in Power Supply Unit

RS stock no. 200-7671

The maximum wattage soldering iron that can be used with this unit is 25 watts at 24V. The unit contains no user serviceable parts and therefore should not be dismantled.

Instructions

1. Select the appropriate soldering iron, and plug it into the power supply unit using the miniature 3-pin plug.
2. Plug in the power supply unit into the voltage supply.
3. Place the soldering iron into a stand and allow to heat up.
4. The soldering iron is now ready to use.

RS Components shall not be liable for any liability or loss of any nature (howsoever caused and whether or not due to RS Components negligence) which may result from the use of any information provided in **RS** technical literature.

