

OPTIBELT SERVICE CASE BASIC



This five-pieces **Service case BASIC** provides the user with a complete set of standard equipment for occasional use.

The SG02 welding tool has a longer warm-up phase than the premium model and is suitable only for PU belts that can be welded using the two corresponding guiding clamps as required.

To ensure the perfect cut for optimum welding results, the set also includes a pair of shears as well as a side cutter for removing the weld seam.



Shears AS02 for cutting round belts and V- belts.



Guiding clamps FZ01 for round belts with diameters of up to 10mm and V- belts profiles up to 10 (Z).



Welding tool SG02 for PU 290- 300°C power supply : 230V.



Guiding clamps FZ02/3 for round belts with diameters from 8mm and V-belts profiles up to 32 (D).



Side cutter SE02 for removing the weld seam.