SYMBOL DEFINITION		NO MISSING SYMBOL
A DIMENSION WITHOUT AN INSPECTION REPORT SYMBOL CODE DOES NOT REQUIRE INSPECTION. IT MAY BE CONTROLLED ON THE INDIVIDUAL COMPONENT DRAWING.	TOTAL NO OF INSPECTIONS REQUIRED: 29	NO MISSING SYMBOL NUMBER
	LAST NO. USED: 16	

REVISION HISTORY													