Digital torquemeter SAUTER DB

SAUTER

PREMIUM ★★★

Convenient way to test the torque of tools

Features

- **1** Particularly suitable for testing torque wrenches, electric hand screwdrivers and cordless screwdrivers
- **2** **Torque pick-up system** for dynamic testing of electric screwdrivers
- **Metal housing** for continuous use in tough environmental conditions
- **Capacity display:** A bar lights up to show how much of the measuring range is still available.
- **LCD graphics display** with backlight
- **Rubber feet with anti-slip feature** at SAUTER DB 0.5-4 up to DB 10-3
- **3** **Stable mounting plate** for solid fixation at SAUTER DB 20-3 up to DB 500-2
- **USB** and **RS-232** data interfaces included
- Scope of delivery: Torque pick-up, sturdy carry case, mounting plate (models with [Max] ≥ 20 Nm)
- **Internal data memory** saves up to 500 measurements. The memory contents can be transferred to the PC using optional software
- **Peak hold function** to capture the peak value or **Track-Funktion** for continuous display of measurement
- **Can be used in both directions of rotation**
- **Measuring with tolerance range (limit-setting function):** Upper and lower limiting can be programmed individually. The process is supported by an audible and visual signal
- **AUTO-OFF function**

Technical data

- Backlit LCD graphics display
- Units can be selected: Nm, lbf-in, kgf-cm, kgf-m, ft-lbf
- Precision: ± 0,5 % of [Max]
- Measuring frequency: 1000 Hz
- Usable measuring range: 5–100 % of [Max]
- Overload protection: 150 % of [Max]
- Rechargeable battery pack integrated, standard, operating time up to 18 h without backlight, charging time approx. 14 h
- Overall dimensions W×D×H 200×100×50 mm
- Net weight approx. 3 kg

Accessories

- **Plug-In for data transfer of measuring** data from the measuring instrument and transfer to a PC, e.g. in Microsoft Excel®, SAUTER AFI-1.0
- **Force-time data transfer software** for graphical representation on the PC and data transfer to Microsoft Excel®, SAUTER AFH FAST
- **RS-232/PC connection cable** SAUTER FL-A04
- **USB/PC connection cable** SAUTER FL-A01

STANDARD
PEAK | MEMORY | RS 232 | USB | STATISTIC | UNIT | TOL | ACCU | 230 V | 1 DAY

OPTION
SOFTWARE | ISO +4 DAYS

Model	Measuring range	Readout	Tool fitting		Option
					Factory calibration certificate
	[Max]	[d]			
SAUTER	Nm	Nm	mm/Inch		KERN
DB 0.5-4	0,5	0,0001	20 mm & 3/8"	🔴	961-120
DB 1-4	1	0,0002	20 mm & 3/8"	🔴	961-120
DB 5-3	5	0,001	20 mm & 3/8"	🔴	961-120
DB 10-3	10	0,002	20 mm & 3/8"	🔴	961-120
DB 20-3	20	0,005	20 mm & 3/8"	🔴	961-120
DB 50-2	50	0,01	20 mm & 3/8"	🔴	961-120
DB 100-2	100	0,02	3/8"	🔴	961-120
DB 200-2	200	0,05	1/2"	🔴	961-120
DB 500-2	500	0,05	3/4"	🔴	961-120

🔴 Price reduction

SAUTER Pictograms:

SAUTER

Adjusting program (CAL):
For quick setting of the balance's accuracy. External adjusting weight required.

Calibration block:
standard for adjusting or correcting the measuring device.

Peak hold function:
capturing a peak value within a measuring process.

Scan mode:
continuous capture and display of measurements.

Push and Pull:
the measuring device can capture tension and compression forces.

Length measurement:
captures the geometric dimensions of a test object or the movement during a test process.

Focus function:
increases the measuring accuracy of a device within a defined measuring range.

Internal memory:
to save measurements in the device memory.

Data interface RS-232:
bidirectional, for connection of printer and PC.

Data interface USB:
To connect the balance to a printer, PC or other peripheral devices.

Data interface Infrared:
To transfer data from the balance to a printer, PC or other peripheral devices.

Control outputs (optocoupler, digital I/O):
to connect relays, signal lamps, valves, etc.

Analogue interface:
to connect a suitable peripheral device for analogue processing of the measurements.

Statistics:
using the saved values, the device calculates statistical data, such as average value, standard deviation etc.

PC Software:
to transfer the measurements from the device to a PC.

Printer:
a printer can be connected to the device to print out the measurements.

GLP/ISO record keeping:
of measurements with date, time and serial number. Only with SAUTER printers.

Measuring units:
Weighing units can be switched to e.g. non-metric at the touch of a key. Please refer to website for more details.

Measuring with tolerance range (limit-setting function):
Upper and lower limiting can be programmed individually. The process is supported by an audible or visual signal, see the relevant model

ZERO:
Resets the display to "0".

Battery operation:
Ready for battery operation. The battery type is specified for each device.

Rechargeable battery pack:
rechargeable set.

Mains adapter:
230V/50Hz in standard version for EU. On request GB, AUS or USA version available.

Power supply:
Integrated, 230V/50Hz in EU. More standards e.g. GB, AUS or USA on request.

Motorised drive:
The mechanical movement is carried out by a electric motor.

Motorised drive:
The mechanical movement is carried out by a synchronous motor (stepper).

Fast-Move:
the total length of travel can be covered by a single lever movement.

DAkkS calibration possible:
The time required for DAkkS calibration is shown in days in the pictogram.

Factory calibration:
The time required for factory calibration is specified in the pictogram.

Package shipment:
The time required for internal shipping preparations is shown in days in the pictogram.

Pallet shipment:
The time required for internal shipping preparations is shown in days in the pictogram.

Your SAUTER specialist dealer: