



3M™ Fibrlok™ Splice Kit
with Cleaver 2559-C



3M™ Cleaver 2534

3 M™ FIBRLOK™ SPLICE KIT WITH CLEAVER 2 5 5 9 -C

The 3M Fibrlok splice kits are available with (2559-C) and without (2559) a fiber cleaver and contain all the materials needed to terminate 3M Fibrlok splices whether it be a singlemode or multimode splice. Detailed instructions are provided. Also included in the kits are the 3M™ Fibrlok™ II Assembly Tool 2501 and 3M™ Fibrlok™ 250µm Assembly Tool 2504G, simple-to-use tools designed for fast and easy installation.

The 2559-C kit contains:

- **2501 assembly tool for 3 M™ Fibrlok™ II 2529**
- **2504G assembly tool for 3 M™ Fibrlok™ 250µm Splice**
- **3 M™ Fiber Cleaver 2534 (not included in 2559 kit)**
- **3 M™ Fiber Stripping Tool 6365-ST**
- **3 M™ Kevlar Snips (scissors) 6365-KS**
- **Lint free cloths (100/pkg.)**
- **Cleaning alcohol bottle**
- **Fibrlok II splice 2529 (6 each)**
- **Fibrlok 250µm 2540G (5 each)**
- **3 M™ Fibrlok™ II Splice/Holder 2539 (2 each)**

ORDERING INFORMATION

3 M Fibrlok Splice Kits and Accessories

PRODUCT NUMBER	DESCRIPTION	PACKAGING	MIN. ORDER	UPC
KITS				
2559-C	Fibrlok splice kit with fiber cleaver	1/cs.	1 each	051115-25801
2559	Fibrlok splice kit without fiber cleaver	1/cs.	1 each	051115-25800
Replacements for 3 M Fibrlok Splice Kit				
2501	Assembly tool required for Fibrlok II splice 2529	1/cs.	1 each	054007-57125
2504G	Assembly tool required for Fibrlok 250µm 2540G	1/cs.	1 each	051115-22686
2534	Fiber Cleaver	1/cs.	1 each	051115-25802
6365-ST	Stripping Tool	1/cs.	1 each	051115-16200
6365-KS	Kevlar Snips	1/cs.	1 each	051115-16202
05-00017	Lint free cloths	100/pkg.	1 pkg.	054007-48999