



2-M3 TAPS
When attaching a weight, make sure that the screw tip does not enter more than 5mm from the surface of the sheet metal.

Dimensions of Mount

Entaniya