

Northbrook, Illinois • (847) 272-8800  
Melville, New York • (516) 271-6200  
Santa Clara, California • (408) 985-2400  
Research Triangle Park,  
North Carolina • (919) 549-1400  
Camas, Washington • (360) 817-5500



COOPER INDUSTRIES INC  
BUSSMANN DIV  
MR W CURTIS  
PO BOX 14460  
ST LOUIS MO 63178

Your most recent listing is shown below. Please review this information and report any inaccuracies to the UL Engineering staff member who handled your UL project.

IZLT2 August 28, 1997  
Component - Fuseholders, Cartridge Fuse

COOPER INDUSTRIES INC BUSSMANN DIV

E14853 (N)  
(E - cont. from D card)

Model Nos. 15087, 15087-1K0797.  
Cat. Nos. BCCS-6033-PQ, -SQ.  
Cat. Nos. HBH, HBV, HBW followed by -I or -M. Cap assemblies FBI and FBM.  
Cat. No. A.  
Cat. Nos. E, F.  
Model Nos. R25100, R25200, R60100, R60200 followed by -1STR.  
Model Nos. R25600, R60600 followed by -1STR or -1STRM.  
Cat. Nos. HTC-10M, -15M, -35M, -40M, -45M, -50M, -55M, -70M.  
Cat. No. MSC-10.  
Model Nos. J60100, -200, -600 followed by 1, 2 or 3, followed by STR.  
Series BH.  
Cat. No. OPM-1038.  
Cat. No. OPM-1038C.  
Cat. No. OPM-1038C2.  
Cat. No. HGC.  
Cat. Nos. J70100-1CR, -1CRA, -2CR, -2CRA, -3CR, -3CRA.

Reports: November 17, 1982; November 6, 1991; March 14, 1985; December 11, 1991; December 12, 1991; August 4, 1992; August 5, 1992; October 21, 1992; December 1, 1992; October 7, 1993; March 31, 1995; April 3, 1996; April 4, 1996; April 5, 1996; May 7, 1996; November 18, 1996.

Replaces E14853E dated June 18, 1997.

579980001

Underwriters Laboratories Inc.®

(Cont. on F card)

D1I/0182376  
94

For information on placing an order for UL Listing Cards in a 3 x 5 inch card format, please refer to the enclosed ordering information.

UNDERWRITERS LABORATORIES INC.

A not-for-profit organization  
dedicated to public safety and  
committed to quality service