

Amphenol Commercial Products - Product Change Notice (PCN)



PCN Number	PCN-C05076
Description of Change	FLH crimp contact plating changed from bright to matte tin.
Reason for Change	Proactive design improvement to reduce the risk of tin whisker formation. Resolves logistical issues associated with bright tin plating process.
Summary of Changes (between new and old part)	All bright tin plating replaced with matte tin plating. Change does not affect overall connector performance.
Traceability Guidelines (lot code / date code, markings, ship date...)	Date codes that include or postdate 2522 (YYWW). Consult an Amphenol representative for any shipment specific inquiries.
Last Time Buy Date	N/A
Datasheet attached? & Filename(s)	N/A
Qual test data attached? & Filename(s)	N/A

Customer Part Number	Amphenol Old Part Number	Amphenol New Part Number	PCN Effectivity Date			
	FLH-PC136-T01	No Change	See traceability guidelines above			
	FLH-PC136-1-T01					
	FLH-SC136-T01					
	FLH-SC136-1-T01					