COBRA

ESSENTIAL WRAP-AROUND COMFORT

The essential all rounder with a panoramic visual field! Wrap-around fit without any visual interference, COBRA offers 180° vision and perfect optical quality.

#PLATINUM







PSLCOBR112



ECO-PACKAGING:

Guaranteed plastic-free, this GDGREEN packaging is respectful of the environment. The products are wrapped in tissue paper and then stored in recycled and recyclable cardboard boxes. The user instructions are printed with vegetable ink directly onto the packaging to reduce waste.

- **+** UPPER PROTECTION
- **→** → LATINUM SCRATCH AND FOG RESISTANT COATING
- SUSTAINABLE PACKAGING
- FOAM AND STRAP FOR INCREASED COMFORT
- UNIVERSAL FIT
- PIVOTING ADJUSTABLE STRAP



GUBRA

ESSENTIAL WRAP-AROUND COMFORT

MODEL	VERSIONS	REFERENCES	LENS MARKING	FRAME MARKING	COATINGS
COBRA	Clear	PSGCOBR104	2C-1.2 😭 1 BT KN €€		Anti-scratch/Anti-fog (⁺P)
	Extra lens	PSLCOBR112	2C-1.2 😭 1 BT KN €€	-	Anti-scratch/Anti-fog (+7)

LENS MARKINGS

Optical class symbols:

1. Continuous work

Mechanical strength symbols:

- B. Medium energy impact, resists a 6 mm, 0.86 g ball at 120 m/s
- T. The letter T, immediately after the mechanical strength symbol, authorises use for high speed particles at extreme temperatures.

Others symbols:

- K. Resistance to surface damage by fine particles (optional)
- N. Resistance to fogging (optional)
- C€ European standard ☐ Manufacturer name

FRAME MARKINGS

EN 166: guaranteed minimum resistance of the protective eyewear against everyday risks including dropping the protective eyewear onto the ground, ageing by light exposure, exposure to heat or corrosion etc.

- F. Low energy impact, resists a 6 mm, 0.86 g ball at 45 m/s Maximum protection for glasses.
- B. Medium energy impact, resists a 6 mm, 0.86 g ball at 120 m/s
- T. The letter T, immediately after the mechanical strength symbol, authorises use for high speed particles at extreme temperatures.
- C€ European standard ☐ Manufacturer name

Bollé Safety product approval certificates to CE standards will be sent on request.

CLEANING AND STORAGE

CLEANING: The lenses should be cleaned regularly. Bollé Safety recommends only using the B-clean lens cleaning system.

MAINTENANCE: Pitted, scratched or damaged lenses must be replaced by replacing the complete product. If the frame is damaged also replace the complete product. After each use it is recommended to keep the spectacles or goggles in a microfiber pouch or rigid case.

STORAGE: All products must be stored in a dry and clean environment.

PACKAGING AND EAN13 CODE					
	PSGCOBR104	PSLCOBR112			
Inner box	3660740113247 (20)	3660740113599 (60)			
Outer pack	3660740213244 (240)	3660740213596 (720)			



Eco packaging: Guaranteed plastic-free, this packaging is respectful of the environment. The products are wrapped in tissue paper and then stored in recycled cardboard boxes. Inner box: 56x18x9cm // Outer pack: 76x58x30cm - Not available in single sale format.

CARACTERISTICS				
LENSES	PC - 2,2 mm - Curve 9			
FOAM	EVA			
STRAP	15mm adjustable			
SPARE LENS	Yes			















Non-contractual pictures 01/12/2021

Europe Bollé Safety 34 rue de la Soie 69100 Villeurbanne - France Tél.: 00 33 (0) 4 78 85 23 64 Fax: 00 33 (0) 4 78 85 28 56 contact@bolle-safety.com

Bollé Safety AU Pty Limited 32-40 Fairchild St Heatherton VIC 3202 Australia Tel: 1300 138 098 sales@bollesafety.com.au

