Test Procedure for MC34063 Inverting Regulator (Leaded) Demonstration Board

**ON Semiconductor** 



11/11/2003

Table 1: Required Equipment		
Three Black Test Leads	Three Red Test Leads	100mA load (or 33 ohm, 1W resistor)
12 VDC Power Supply	MC34063 Inverting Regulator	Digital Multimeter
Four Alligator Clips		




Figure 1: Test Procedure for MC34063

- 1. Attach 50 mA load (or 240 ohm, 1 W resistor) to connector P602.
- 2. Attach 5 VDC source to connector P601 observe polarity.
- 3. Turn on 5 VDC source.
- 4. Measure DC output voltage at connector P602.
- 5. DC voltage should be -12.35V + 0.3V.
- 6. Remove load.
- 7. Measure DC output voltage at connector P602.
- 8. DC voltage should be -12.35V + 0.3V.
- 9. Remove 5 VDC source and disconnect load test complete.