





C



REVISIONS

P	LTR	DESCRIPTION	DATE	DWN	APVD
		SEE SHEET 1			


PACKAGING



25 PCS/Bundle




50pcs/Bag
drying agent: 1pcs/Bag





Number of label

- Importance of check:
- 1.Check whether the product is out of shape before packing.
 - 2.When packing, handle the product lightly to avoid product distortion.
 - 3.After packed, check whether there is any miss and whether the product is placed in the correct direction.
 - 4.If there are unfilled boxes, fill them with buffer materials.
 - 5.After the Carton is sealed, check whether the label is properly affixed, clean, legible, and whether the label content is correct.
 - 6.Carton size (604010011) : L340*W240*H230mm

Package materials			Packing Spec		
Items	P/N	QTY	PCS/Bag	Bag/Box	PCS/Box
Carton	604010011	1	50	40	2000
Small PE bag	840000511	40			
Waterproof bag	840000502	1			
Foam		2			
Drying agent	708040129	40			



40 Bag/Box
(2000PCS/Box)



Carton Label

THIS DRAWING IS A CONTROLLED DOCUMENT.		DWN	TE Connectivity			
		CHK				
DIMENSIONS:		APVD	NAME			
		PRODUCT SPEC				
		APPLICATION SPEC				
		WEIGHT	SIZE	CAGE CODE	DRAWING NO	RESTRICTED TO
			A2	C-		
			SCALE	SHEET	OF	REV