

Product Change Notice

Issue Date: 31-January-2025

Change Description:

Introduce Alternate Lead Frame Source

Parts Affected:

HSMA-A100-Q00J1	HSMC-A100-Q00J1	HSMH-A100-P80J1	HSMG-A100-M42J1
HSMA-A100-Q0PJ1	HSMC-A100-Q40J1	HZMH-A100-L00J1	HZMG-A100-H01J1
HSMA-A100-R40J1	HSMC-A100-Q70J1	HZMH-A100-N00J1	HZMG-A100-J02J1
HSMA-A100-R45J1	HSMC-A100-R00J1	HSMD-A100-J00J1	HZMG-A100-L02J1
HSMA-A100-R4WJ1	HSMC-A101-R70J1	HSMD-A100-L00J1	HZMG-A100-K82J2
HSMA-A100-R6WJ1	HSMC-A101-S00J1	HSMD-A100-L8PJ2	HZMG-A100-M42J1
HSMA-A100-R7NJ1	HSMC-A101-S30J1	HSMD-A100-N40J1	QSMG-A10A-J02J1
HSMA-A101-R8WJ1	HSMC-A101-S40J1	HZMD-A100-J00J1	HSMJ-A100-Q00J1
HSMA-A101-S00J1	HSMC-A101-S80J1	HZMD-A100-L00J1	HSMJ-A100-R40J1
HSMA-A101-S3WJ1	HZMC-A100-Q00J1	HZMD-A100-N40J1	HSMJ-A100-T40J1
HSMA-A101-S70J1	HZMC-A100-R00J1	HSML-A100-Q00J1	HSMJ-A101-S00J1
HSMA-A101-T2WJ1	HZMC-A100-R20J1	HSML-A100-R7YJ1	HZMJ-A100-Q00J1
HSMA-A160-S7WJ1	HZMC-A101-S00J1	HSML-A101-S00J1	HZMJ-A100-R40J1
HZMA-A100-Q00J1	HZMC-A100-S30J1	HSML-A101-S40J1	HZMJ-A101-S00J1
HZMA-A100-R2WJ1	HZMC-A101-S30J1	HSML-A101-S4WJ1	HSMV-A100-T00J1
HZMA-A100-R40J1	HZMC-A101-S40J1	HZML-A100-Q00J1	HZMV-A100-T00J1
HZMA-A100-R45J1	HZMC-A101-S80J1	QSML-A101-S00J1	ASMT-UHB4-PU802
HZMA-A101-S00J1	QSMC-A100-Q00J1	QSML-A118-T00J1	HSMM-A100-S00J1
HZMA-A101-S70J1	QSMC-A101-S00J1	QSML-A118-T70J1	HSMM-A100-U4PJ1
QSMA-A100-P5PJ2	QSMC-A101-S30J1	QZML-A102-S00J1	HSMM-A100-V4PJ1
QSMA-A10A-Q00J1	QZMC-A100-Q00J1	HSME-A100-L01J1	HSMM-A101-R00J1
QSMA-A133-T2WJ1	QZMC-A102-R00J1	HSME-A100-L7YJ1	QSMM-A149-S00J1
QSMA-A134-S3VJ1	AZMT-URB4-PU802	HSME-A100-M02J1	QZMM-A102-S00J1
QZMA-A100-P5PJ2	HSMZ-A100-R00J1	HSME-A100-M3PJ1	QZMN-A102-R00J1
QZMA-A102-S00J1	HSMZ-A100-T00J1	HSME-A100-M4PJ1	ASMT-UGB5-NW702
HSMU-A100-R00J1	HSMZ-A100-T70J1	HSME-A100-N82J1	ASMT-UGB5-NW7Y2
HSMU-A100-S00J1	HZMZ-A100-R00J1	HSME-A100-P32J1	HSMN-A100-P00J1
HZMU-A100-S00J1	HSMS-A100-J00J1	HSME-A100-Q3TJ1	HSMN-A100-R00J1
ASMT-UAB4-PU802	HSMS-A100-L00J1	HZME-A100-N82J1	HSMN-A100-ROYJ1
AZMT-UAB4-PU802	HSMS-A100-L50J2	HZME-A100-Q3TJ1	HSMN-A100-S00J1

HSMY-A100-J00J1	HZMS-A100-J00J1	QSME-A10A-L01J1	HSMN-A100-S4YJ1
HSMY-A100-L00J1	HZMS-A100-L00J1	HSMG-A100-H01J1	HSMN-A101-N00J1
HZMY-A100-J00J1	HZMS-A100-L50J2	HSMG-A100-J02J1	ASMT-UBB5-NS8Q2
HZMY-A100-L00J1	QSMS-A10A-J00J1	HSMG-A100-L02J1	ASMT-UBB5-NT3Y2
QSMY-A10A-J00J1	HSMH-A100-L00J1	HSMG-A100-K82J2	HSMW-A100-V40J1
HSMC-A100-K50L2	HSMH-A100-N00J1	HSMG-A100-L32J2	

Description and Extent of Change:

To introduce alternate lead frame source for the part numbers listed above.


Reasons for Change:

Assurance of supply

Effect of Change on Fit, Form, Function, Quality, or Reliability:

There is no change in product fit, function, quality or reliability of the final product.

The form difference is as below. Package dimensions and drawings in the data sheet are not affected.





Effective Date of Change:

The shipment with above change will commence 90 days after issuance date above.

Parts identification:

PCN number identification will be printed on the mother label to identify the lot has changed to new source of lead frame as indicated below.



Qualification Data:

No change in reliability performance. Qualification data will be available upon request.

Please contact your Broadcom field sales engineer or Contact Center for any questions or support requirements. Please acknowledge the receipt of the notice within 30 days of delivery. Lack of acknowledgement within 30 days constitutes acceptance of the change per JEDEC J-STD-046.