

When joining MT-RJ connectors, one connector must always be male with pins and one must be female without pins.




Fig. 3.2 MT-RJ ferrule alignment method.