

## For etching machines

### 48 Volts Models

	Item Code
<del>50W Heating resistance for BB 28, BB 38, BB 48</del>	<del>DCP 108</del>
Pump for BB 28, BB 38, BB 48	DCP 103
Transformer for BB 28, BB 38, BB 48	DCP 110
Diffusor for BB 28, BB 38	DCPD 3
Diffusor for BB 48	DCP 127

### 220 Volts Models

	Item Code
50W Heating resistance for DP41, BB2, BB4, DP36, DP:	DCP 24
100W Heating resistance for DP 8, DP 9, DP 86, BB 3	DCP 25
200W Heating resistance for DP 10	DCP 26
300W Heating resistance for EP 38, EP 38 T, DP 13	DCP 28
Pump for BB 2, BB 3, DP 36, DP 37, BB 4	DCPD 4
Diffusor for BB 4	DCP 127
Diffusor for DP 36, DP 37	DCP 128
Diffusor for BB 2, BB 3	DCPD 3
Set of bavettes for DP 8, DP 9	DCP 57
Set of bavettes for DP 10	DCP 58
Set of bavettes for DP 13	DCP 59
Set of bavettes for EP 38, EP 38 T	DCP 122
Motor for DP8, DP9, DP10, DP86, DP13, DP88	DCP 81
Motor for EP 38, EP 38 T	DCP 836
Pump for DP 8, DP 9, DP 10	DCP 82
Pump for DP 13	DCP 83
Pump for DP 86	DCP 84
Pump for EP 38	DCP 833
Pump for EP 38 T	DCP 835
Threaded nozzles for DP13, EP 38, EP 38 T, DP 86, DP 88	DCP 77
Non threaded nozzles for DP 8, DP 9, DP 10	DCP 78
PVC screw 6 x 13 for DP 13	DCP 79
PVC screw 6 x 25 for DP 8, DP 9, DP 10	DCP 80