

Product Change Notification (PCN)

PCN #: 2D-2026

Date: February 06, 2026

1 Products Affected

Ezurio Part Number	Description
453-00045R	Module, Sterling LWB5+, Chip Antenna, Tape & Reel
453-00045C	Module, Sterling LWB5+, Chip Antenna, Cut Tape
453-00046R	Module, Sterling LWB5+, MHF4, Tape & Reel
453-00046C	Module, Sterling LWB5+, MHF4, Cut Tape
453-00047R	Module, Sterling LWB5+, Trace Pin, Tape & Reel
453-00047C	Module, Sterling LWB5+, Trace Pin, T
453-00048	Module, Sterling LWB5+, M.2, Key E, SDIO, UART
453-00049	Module, Sterling LWB5+, M.2, Key E, USB, USB
453-00045-K1	Development Kit, Sterling LWB5+, Chip Antenna
453-00046-K1	Development Kit, Sterling LWB5+, MHF4
453-00048-K1	Development Kit, Sterling LWB5+, M.2, Key E, SDIO, UART
453-00049-K1	Development Kit, Sterling LWB5+, M.2, Key E, USB, USB
450-00179	Assembly, PCBA, Sterling LWB5+, USB Adapter
450-00179B	Assembly, PCBA, Sterling LWB5+, USB Adapter, Bulk
450-00137	Assembly, Sterling LWB5+, USB Adapter
450-00137B	Kit, Sterling LWB5+, USB Adapter, Bulk

2 Description of Changes

All changes have been applied to the part numbers listed above:

- Update device label to include KC ID and logo to identify South Korea certification

3 Reason for Change

- To ensure compliance with South Korea certification standards


4 Anticipated Impact of the Change

- There is no form, fit or functional change caused by this PCN Method of Identifying the Changed Product


5 Method of Identifying the Changed Product

5.1 Update Labels


- 453-00045R/453-00045C/453-00046R/453-00046C/453-00047R/453-00047C
 - On the device laser-etching adds KC logo and ID




- 453-00048/453-00049
 - On the device laser-etching adds KC ID and logo




- 453-00045-K1/453-00046-K1
- On the PCBA, the module adds KC ID and logo




- 453-00048-K1/453-00049-K1
- On the M.2 module, the module adds KC ID and logo



- 450-00179/450-00179B
- On the PCBA, module adds KC ID and logo



- 450-00137/450-00137B
 - On the PCBA, module adds KC ID and logo on the shielding
 - There is no laser etching change and major revision change on the product enclosure



6 Factory Effectivity Date

6.1 Factory Effectivity Date

These changes will be implemented into manufacturing starting from Date Codes, as outlined below for each product variant. The date code is shown on each label, as format SSYYWWD.

SS = Supplier code

YY = last two numbers of the year (ex: 18=2018, 19=2019)

WW = Week of the year

D = day of the week (ex: Sun=1, Mon=2, Tue=3, Wed=4, Thu=5, Fri=6, Sat=7)

Ezurio Part Number	Factory Effectivity - Date Codes
453-00045R	0926121
453-00045C	0926121
453-00046R	0926121
453-00046C	0926121
453-00047R	0926121
453-00047C	0926121
453-00048	0926151
453-00049	0926151
453-00045-K1	1026151
453-00046-K1	1026151
453-00048-K1	1026151
453-00049-K1	1026151
450-00179	1226231
450-00179B	1226231
450-00137	1226231
450-00137B	1226231

6.2 Inventory Management

This will be a running change.

7 Contact Information

Headquarters Ezurio
50 S Main St., Suite 1100
Akron, OH 44308 USA
Tel: 1(330) 434-7929
Fax: 1(330) 434-7931

Website www.ezurio.com

Sales / Support Contact <https://www.ezurio.com/contact>

Product Change Notices (PCNs) will be distributed at the discretion Ezurio. Occasionally, Ezurio may adjust product revision levels for internal tracking purposes only, and customers may not receive formal notifications associated with those revision changes.