

PELTOR™

G2000 Hard Hat with
UViCATOR™
sensor



HAS YOUR HARD HAT BEEN OUT IN THE SUN TOO LONG?

When working outdoors, the sun's ultraviolet (UV) rays can start to damage most hard hats, eventually reducing performance and putting the safety of the wearer at risk. Unfortunately, it is difficult to tell the difference between a new and a UV-aged hard hat. The Peltor™ G2000 hard hat with Uvicator™ sensor now makes it possible to tell when a hard hat should be replaced due to UV exposure.

- Designed specifically for outdoor use
- Patented Uvicator™ sensor changes color when exposed to UV light
- Hearing protector recess and accessory slots for protective earmuffs and communication headsets
- Meets requirements of ANSI Z89.1-2003 Type I, Class C

3M

G2000 Hard Hat with UVicator™ sensor

Damage to a hard hat is mainly caused by factors which are often visible, such as impacts, rough treatment, wear and chemical degradation. But there is a hidden factor that is not always visible: the sun.

The Peltor™ G2000 hard hat with Uvicator™ sensor provides a visual indicator to wearers that it's time to replace their hard hat due to extended UV exposure. The built-in indicator is shaped like a small clock. At the outset, it is bright red. As the hard hat is exposed to UV light, the indicator will gradually fade. When it has turned completely white, it's time to replace the hard hat. Peltor G2000 hard hats meet the requirements of ANSI Z89.1-2003, Type I, Class C.



Product Code	Description	UPC	Case Packaging	Case Weight (lbs.)	Case Dimensions (L x W x H)
PG2008ORUV	Peltor G2000 orange hard hat with Uvicator™ sensor, 4-PT pinlock suspension	0 93045 93243 6	1 hard hat/case	1.4	12.75 x 9.5 x 8.0
PG2008MUV	Peltor G2000 Lumberjack Kit - orange hard hat with Uvicator™ sensor, V4A metal mesh multi-visior, H31P3E earmuff	0 93045 93242 9	1 kit/case	2.1	12.75 x 9.5 x 8.0



**3M Occupational Health and
Environmental Safety Division**
3M Center
St. Paul, MN 55144-1000
www.3M.com

For More Information
Sales Assistance: 1-800-328-1667
Technical Assistance: 1-800-243-4630
Website: www.3M.com/OccSafety

⚠ WARNING:

These hard hats provide limited protection only. Misuse or failure to follow warnings and instructions may result in serious personal injury or death. For proper use, see supervisor, read instructions and warnings on package, or call Technical Service at 1-800-444-4774.

Aearo Technologies LLC . 8001 Woodland Drive . Indianapolis, IN . 46278
© 2009 3M Company. All rights reserved. 3M, Peltor and Uvicator are trademarks of 3M Company.