

Date 7/October/2019


To: PIEU

Notice: **Not Recommended for New Designs**

We appreciated your continued patronage and interest in Panasonic's Products.
This is Notice to inform you of NRFND as below.


【Detail】

About this Notice	Electric Double Layer Capacitors (Wound type) are not recommended for new designs.
Affected Models	See attached file Series: EECHZ~ / EECHW~ / EECHL~
Effective date	Immediate



Kazuto NISHIDA

Plant Superintendent
Uji Plant
Device Solutions Business Division
Industrial Solutions Company
Panasonic Corporation



Masaki YOSHINO

Department Director
Strategic Marketing Department
Device Solutions Business Division
Industrial Solutions Company
Panasonic Corporation

EDLC WOUND TYPE

No Recommend for New Design in 2019

Series	Part No.	Φ	Max Operating Voltage (DC)	Capacitance (F)
HZ	EECHZ0E335	8.0	2.5	3.3
HZ	EECHZ0E475	10.0	2.5	4.7
HZ	EECHZ0E106	10.0	2.5	10
HW	EECHW0D226	18.0	2.3	22
HW	EECHW0D306	18.0	2.3	30
HW	EECHW0D506	18.0	2.3	50
HW	EECHW0D706	18.0	2.1	70
HL	EECHL0E506	18.0	2.7	50
HL	EECHL0E107	18.0	2.7	100
HL (85°C)	EECHL0E255	8.0	2.7 (2.5)	2.5
HL (85°C)	EECHL0E405	10.0	2.7 (2.5)	4.0
HL (85°C)	EECHL0E755	10.0	2.7 (2.5)	7.5