Melville, New York • (516) 271-6200

Santa Clara, California • (408) 985-2400

Research Triangle Park. North Carolina • (919) 549-1400

Camas, Washington • (360) 817-5500



CROUZET CORP MR D F WOOD 3237 COMMANDER DR CARROLLTON TX 75006



Your most recent listing is shown below. Please review this information and report any inaccuracies to the UL Engineering staff member who handled your UL project.

> **NRNT8** November 2, 1998 Component - Switches, Industrial Control Certified For Canada

**CROUZET CORP** E46203

(B - cont. from A card)

Open type, Solid-state relays for use in industrial applications.

Model IAC followed by B, with or without A, with or without -1 through -999.

Model IDC with or without prefix M or SM, followed by 5, 15 or 24, with or without any combination of F, N, I or V, with or without L, with or without -1 through -199, -200 or -201 through -999; -1 through

Model IDCB with or without A, with or without -1 through -999.

Model SM-IDC5-1.

Model 8411 followed by 0, 1 or 3, followed by 1 or 2, followed by 1, 2 or 3, followed by 0, 1 or 2. Model ODC with or without prefix M or SM, with or without 5, 15 or 24, with or without V, with or without any combination of A, F or V, with or without L, with or without 25, with or without -1 through

Model ODCB with or without -1 through -999.

Model 8411 followed by 0, 1 or 3, followed by 4, followed by 1, 2 or 3, followed by 0, 1 or 2.

Model 84111910 and 84111911.

Model GA1, followed by -2, -4 or -6, followed by B, followed by 01 or 02, with or without -1 through -999, with or without V.

Reports: April 26, 1982; June 23, 1982; June 23, 1982; June 23, 1982; June 23, 1982; June 24 1982.

Replaces E46203B dated June 30, 1997. 632610001

Underwriters Laboratories Inc.®

(Cont. on C card) D1I/0322399

For information on placing an order for UL Listing Cards in a 3 × 5 inch card format, please refer to the enclosed ordering information.

UNDERWRITERS LABORATORIES INC.