



Expertise Applied | Answers Delivered

8755 W. Higgins Road

Suite 500

Chicago, IL 60631


www.littelfuse.com

LF PCN# A0096 ATO/Mini Tester Puller Design Change

November 10, 2016

Dear Valued Customer,

Littelfuse is changing two spring pins of ATO/Mini Tester/Puller **B0970019Z** from spring to fixed as shown in below drawing.



Littelfuse is in the process of implementing this change immediately, but the change will be implemented as a running change so customers may continue to receive stock with previous version.

Please contact your local Littelfuse representative if you have any additional questions. We will be pleased to answer any questions you may have. Thank you for your continued support.

Best Regards,

Jenny Kiolbasa

Jenny Kiolbasa

Littelfuse Automotive Business Unit

Passenger Car Products

jkiolbasa@littelfuse.com