



Mounted Wheels and Points

Stock No. 575-201

Pack Quantity 10

Shape No. W220

Max Recommended Operating Speed 25,500 RPM

Spindle Size 6 mmØ

Warning

1. Operating speed quoted is for an overhang of 13mm. Do not exceed the maximum operating speed and overhang of points.
2. Always use eye protection.
3. Check that the bearings and collet of your grinder are not worn.
4. Avoid excessive pressure which could damage the spindle.

Note:

Further information on the correct use of mounted points can be obtained from the Health and Safety Executive Publication Ref. HS(G)17, and the European Safety Code issued by the Federation of European Producers of Abrasive Products (FEPA No. 12GB 74).