



F-840/841/843 ESD FLOOR MAT



Class 10000

These mats drain away static electricity. They also help prevent fatigue.

- They are designed to relieve fatigue from workers in standing operations.
- They also allow spilled liquids to drain away. So they can also be used in wet work areas.
- The mat pieces can be interchanged easily for different work areas.



Example of combination for photograph
 F-840 × 6
 F-841-A × 2
 F-841-B × 2
 F-843-A × 3
 F-843-B × 3

Part No.	Dimensions m	Thickness mm	Surface resistance value	Weight kg
F-840	300(W)×300(D)	10	1×10 ⁶ Ω or less	310
F-841-A	75(W)×375(D)			150
F-841-B				150
F-843-A	75(W)×300(D)			120
F-843-B		120		



edges beveled for casters



A type




B type

Related Products

F-27 GROUND WIRE

- 2mm²×2m
- 2pcs/pack



F-29-1 STUD


- 5pcs/pack



F-29-1

F-28 CONDUCT PLATE

- 10pcs/pack



F-29-2 PUNCH KIT


- 1set/pack (punch and chisel)



F-29-2

F-29 GROUND WIRE

- 1.25mm²×1m
- With 1M current limiting resistor



Conductive mat installation procedure.

1. Use scissors to cut the color mats and rubber mats to suit the area.
2. The grounding



Simply attach the ground wire in contents to the backside of the mat for grounding. The cord has 2 meters extra-long enough to adjust the length. (As a standard of proper grounding, one cord covers the area of 20m²) Use the F-28 Conduct plate(optional) to conduct the neighboring mats. (As a standard, one plate covers a 5 meters.) Also possible to use as simple ground such as hooks or grommets, or alligator clips as contacts.

CUTTERS
 WIRE STRIPPERS
 CRIMPERS
 TWEEZERS
 SCREWDRIVERS & WRENCHES
 METAL WORKING TOOLS
 CASES & BAGS
 TOOL KITS
 SOLDERING TOOLS
 DESOLDERING TOOLS
 MEASURING INSTRUMENTS
 MICROSCOPES & MAGNIFIERS
 STATIC CONTROL
 CLEAN ENVIRONMENT
 CHEMICALS
 MAINTENANCE TOOLS