


Туре	Bi10-M30-Y1X-H1141/S56 4020201 10 mm	
ldent-No.		
Rated operating distance Sn		
Mounting condition	flush	
Assured sensing range	≤ (0,81 x Sn) mm	
Correction factors	$St37 = 1$, $V2A \sim 0.7$, $Ms \sim 0.4$, $AI \sim 0.3$	
Repeatability	≤ 2 %	
Temperature drift	≤ ± 10 %	
Hysteresis	1 10 %	
Ambient temperature	-25…+ 70 °C	
Output function	2-wire, NAMUR	
Switching frequency	≤ 0.5kHz	
voltage	Nom. 8.2 VDC	
Non-actuated current consumption	≥ 2.1 mA	
Actuated current consumption	≤ 1.2 mA	
Approval acc. to	KEMA 02 ATEX 1090X Issue no.4	
Internal inductance (L _i) / capacitance (C _i)	150 nF / 150 μH	
Device designation		
	(max. $U_i = 20 \text{ V}, I_i = 20 \text{ mA}, P_i = 200 \text{ mW}$)	
Housing	threaded barrel, M30 x 1.5	
Dimensions	74.5 mm	
Housing material	Metal, CuZn, chrome-plated	
Material active face	Plastic, PA12-GF30	
Tightening torque of housing nut	75 Nm	
Electrical connection	Connectors, M12 x 1	
Vibration resistance	55 Hz (1 mm)	
Shock resistance	30g (11 ms)	
Protection class	IP67	
Switching state	LED yellow	

- ATEX category II 1 G, Ex zone 0
- ATEX category II 1 D, Ex zone 20
- SIL2 as per IEC 61508
- threaded barrel, M30 x 1.5
- Chrome-plated brass
- 2-wire DC, nom. 8.2 VDC
- output according to DIN EN 60947-5-6 (NAMUR)
- connector M12 x 1

Wiring diagram




Functional principle

Inductive sensors detect metal objects contactless and wear-free. For this purpose they use a high-frequency electromagnetic AC field that interacts with the target. The sensors hosting a ferrite core coil generate the AC field through an LC resonant circuit.



Mounting instructions	minimum distances	
Distance D	2 x B	
Distance W	3 x Sn	
Distance T	3 x B	
Distance S	1.5 x B	
Distance G	6 x Sn	
Diameter of the active area B	Ø 30 mm	





Accessories

Type code	Ident-No.	Short text	Dimension drawing
BST-30B	6947216	Fixing clamp with dead-stop; material: PA6	
QM-30	6945103	Quick-mount bracket with dead-stop; material: Chrome-plated brass Male thread M36 x 1.5. Note: The switching distance of proximity switches can be redu- ced by the use of quick-mount brackets.	
MW-30	6945005	Mounting bracket; material: Stainless steel A2 1.4301 (AISI 304)	5.5. 10.1 11.1 20.5 20.5 20.5 20.5 20.5 20.5 20.5
BSS-30	6901319	Fixing clamp; material: Polypropylene	2,2 10,3
IM1-22EX-R	7541231	Isolating switching amplifier, 2-port; 2 transistor outputs; input for NAMUR signals; selectable ON/OFF mode for wire-break and short-circuit monitoring; adjustable signal flow (NO/ NCmode); removable terminal blocks; 18 mm width; universal voltage supply unit	



Operating manual

Intended use

This device fulfills the directive 94/9/EC and is suited for use in explosion hazardous areas according to EN60079-0:2006, -11:2007, -26:2004 and EN61241-0:2006, -11:2006. Further it is suited for use in safety-related systems, including SIL2 as per IEC 61508. In order to ensure correct operation to the intended purpose it is required to observe the national regulations and directives.

For use in explosion hazardous areas conform to classification

II 1 G and II 1 D (Group II, Category 1 G, electrical equipment for gaseous atmospheres and category 1 D, electrical equipment for dust atmospheres).

Marking (see device or technical data sheet)

ⓑ II 1 G and Ex ia IIC T6 acc. to EN60079-11 and 26 and ⓒ I 1 D Ex iaD 20 T95℃ acc. to EN60079-11 and EN61241-0 and 11

Local admissible ambient temperature

-25...+70 °C

Installation / Commissioning

These devices may only be installed, connected and operated by trained and qualified staff. Qualified staff must have knowledge of protection classes, directives and regulations concerning electrical equipment designed for use in explosion hazardous areas. Please verify that the classification and the marking on the device comply with the actual application conditions.

This device is only suited for connection to approved Exi circuits compliant to EN60079-11 and EN61241-11. Please observe the maximum admissible electrical values. After connection to other circuits the sensor may no longer be used in Exi installations. When interconnected to (associated) electrical equipment, it is required to perform the "Proof of intrinsic safety" (EN60079-14). When employed in safety systems to IEC 51408 it is required to assess the failure probability (PFD) of the complete circuitry.

Installation and mounting instructions

Avoid static charging of cables and plastic devices. Please only clean the device with a damp cloth. Do not install the device in a dust flow and avoid build-up of dust deposits on the device. If the devices and the cable could be subject to mechanical damage, they must be protected accordingly. They must also be shielded against strong electro-magnetic fields. The pin configuration and the electrical specifications can be taken from the device marking or the technical data sheet. In order to avoid contamination of the device, please remove possible blanking plugs of the cable glands or connectors only shortly before inserting the cable or opening the cable socket.

service / maintenance

Repairs are not possible. The approval expires if the device is repaired or modified by a person other than the manufacturer. The most important data from the approval are listed.