



Underwriters Laboratories Inc.®

CARLINGSWITCH INC
MR R BREMER
60 JOHNSON AVE
PLAINVILLE CT 06062

Your most recent listing is shown below. Please review this information and report any inaccuracies to the UL Engineering staff member who handled your Assignment.

WOYR2 January 16, 1992
Component - Switches, Special Use

CARLINGSWITCH INC

E7560 (M)

(Q1-cont. from Q card)

CAT. NO.	AMPS	VOLTS	FREQ	HP
RSC f/b A,B f/b 20,60,70 f/b O, 1,5 f/b R,V,P w/suffixes	20/15 --	125/250 125-250	60 60	-- 3/4
RSC f/b A,B, f/b 21,61,71 f/b O, 1,5 f/b R,V,P w/suffixes	20/15	125/250	60	--
RD22,RA22 f/b O, 1,5,A,B,F f/b M w/suffixes	12/8 --	125/250 125-250	60 60	-- 1/2

Reports: August 24, 1983; August 24, 1983; August 24, 1983.

Cards E7560Q and Q1 (two cards) replace E7560Q dated October 1, 1991.

(Cont. on R card)

255173001 X7987 Underwriters Laboratories Inc.® DIV02051:6 136

For information on placing an order for UL Listing Cards in a 3 x 5 inch card format, please refer to the enclosed ordering information.

UNDERWRITERS LABORATORIES INC.

An independent, not-for-profit organization (es)ling for public safety

333 Pfingsten Road
Northbrook, Illinois 60062-2096, USA
708/272-8800
Telex: 6602543343
FAX No. (708) 272-8129

1285 Wall Whitman Road
Melville, L.I., New York 11747-3081, USA
516/271-6200
Telex: 6852015
FAX No. (516) 271-8258

1655 Scott Blvd.
Santa Clara, California 95050-4169, USA
408/985-2400
Telex: 184219
FAX No. (408) 296-3256

12 Laboratory Drive
P.O. Box 13995
Research Triangle Park,
North Carolina 27709-3995, USA
919/549-1400
Telex: 4937928
FAX No. (919) 549-1842